

Government of Tripura
Office of the Executive Engineer, PWD (R&B)
Dharmanagar Division
Dharmanagar North Tripura



NO.F. 17(6) /EE/DD/9710-11

Dated, the 9th February' 2026.

✓ To
The Principal
Kadamtala H.S School
Kadamtala North Tripura.

Sub:- Submission of Building safety certificate in favour of Kadamtala H.S School.

Ref:- Your office letter No. F.1(19)/PRIN/KHSS/KDL/2022/782, Dated: 05/02/2026


Sir,

Inviting to the letter under reference I am enclosing herewith the building safety certificate for your School with the following enclosures for doing needful action from your end please.

Thanking you

Enclo: As stated above.

Yours faithfully


Executive Engineer PWD (R&B)
Dharmanagar Division
Dharmanagar, North Tripura

Copy to:-

1. The SDO, PWD (R&B), Kadamtala for information.

✓
Executive Engineer PWD (R&B)
Dharmanagar Division
Dharmanagar, North Tripura


PART-II

(To be filled by the SDE)

- a) I have visited the above mentioned school on dated 02.02.2026 and have visually inspected each & every building from all angles of safety. Building wise observations and necessary recommendations are mentioned below:-

Name of the building	Physical observations		Recommendations
Building No.	Type of Structure	Plinth Area (in Sqm.)	Remarks
Building-1	Double Storied RCC framed Structure.	340.00	Building condition is good & safe for the users.
Building-2	Load bearing, pitched roof G.C.I sheet roofing.	1228.00	Minor Mtc. of doors, windows, ceiling is found necessary for smooth functioning of institution.
Building-3	Load bearing, pitched roof G.C.I sheet roofing.	494.70	Minor Mtc. of doors, windows, ceiling is found necessary for smooth functioning of institution.
Building-4	Double Storied RCC framed Structure. (Newly Constructed on 2025)	457.67	The building constructed by Rural Development. Due to delay in external electrification work, the building has not yet been made operational till date.
Total =		2520.37	


- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, under the supervision of a qualified Engineer and this certificate may be re-obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) These building can be safely occupied for normal use if the minor maintenance is carried out as per the recommendations of the undersigned up to 3(three) years.


09/02/2026

Junior Engineer
PWD (R&B) Kadamtala Sub-Division
Kadamtala North Tripura


09.02.2026

Sub-Divisional Officer
PWD (R&B) Kadamtala Sub-Division
Kadamtala North Tripura


Executive Engineer PWD (R&B)
Dharmanagar Division, Dharmanagar